Maryland Historical Trust

Maryland Inventory of Historic Properties number:

The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001. The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following determination of eligibility.			
MARYLAND HISTORICAL TRUST			
Eligibility RecommendedX Eligibility Not Recommended			
Criteria:AB CD Considerations:ABCD _EFGNone			
Comments:			
Reviewer, OPS:_Anne E. Bruder Date:3 April 2001			
Reviewer, NR Program: Peter E. Kurtze Date: 3 April 2001			

dy

MHT No. <u>M:12-51</u>

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

SHA Bridge No. M-150	Bridge name Peach Tree Road over CSXT	Railroad
LOCATION: Street/Road name and num	nber [facility carried] Peach Tree Road	
City/town Sellman	Vicinity	
County Montgomery		
This bridge projects over:	Road Railway_X Water	Land
Ownership: State	County <u>X</u> Municipal	Other
National Register-li	n a designated historic district? Yes isted district National Register-determin district Other	ned-eligible district
Name of district		
BRIDGE TYPE: Timber Bridge: Beam Bridge:	Truss -Covered Trestle Tim	ber-And-Concrete
Stone Arch Bridge	_	
Metal Truss Bridge	<u> </u>	
Movable Bridge: Swing Vertical Lift	Bascule Single Leaf Bascule I Retractile Pontoon	Multiple Leaf
Metal Girder X Rolled Girder Plate Girder	Rolled Girder Concrete Encased	
Metal Suspension		
Metal Arch		
Metal Cantilever		
	Concrete Slab Concrete Beam	Rigid Frame

DESCRIPTION: Setting: Urban	Small town	Rural	X
Describe Setting:			
Bridge No. M-150 carries Peac Tree Road runs north-south, w Sellman, and is surrounded by	hile the CSXT Railroad t	ravels east-west.	gomery County. Peach The bridge is located in
Describe Superstructure and S	ubstructure:		
Bridge No. M-150 is a 3-span, single-lane, concrete encased metal girder bridge. The bridge was built in 1928. The structure is 111 feet long and has a clear roadway width of 14 feet. The superstructure consists of five (5) concrete encased rolled girders which support a concrete deck and a non-structural railing. The girders are 2.5 feet x 11 inches and are spaced 3.2 feet apart. The roadway is carried on the girders. The concrete deck is 7.5 inches thick and it has a concrete wearing surface. The structure has steel angle railings. The substructure consists of two concrete spill-through abutments and two (2) concrete hammerhead piers. The bridge has a Montgomery County sufficiency rating of 49.5.			
According to the 1995 inspection report, this structure is in fair to poor condition with cracking and spalling. The asphalt wearing surface has completely worn on the west side of the bridge. The east side of the bridge has cracking and spalled areas on the east side of the deck. The underside of the deck has open cracks with efflorescence. The concrete encasement has spalled from the bottom of the steel beams. The bottom flanges are exposed and corroding. Both piers and abutments have been patched with gunite.			
Discuss Major Alterations:			
According to the 1995 inspection report, there have been no major alterations to the bridge.			
HISTORY:			
WHEN was the bridge built: This date is: ActualX Source of date: Plaque Other (specify)		imated County bridge file	es/inspection form X
WHY was the bridge built?			
The bridge was constructed in response to the need for more efficient transportation network and increased load capacity.			
WHO was the designer?			
Unknown			
WHO was the builder?			
Unknown			

WHY was the bridge altered?

N/A

Was this bridge built as part of an organized bridge-building campaign?

There is no evidence that the bridge was built as part of an organized bridge building campaign.

SURVEYOR/HISTORIAN ANALYSIS:

This bridge may have National	Register signifi	cance for its	association with:
A - Events	B- Person		_
C- Engineering/architec	tural character	X	_

The bridge is eligible for the National Register of Historic Places under Criterion C, as a significant example of metal girder construction. The structure has a high degree of integrity and retains such character-defining elements of its type as concrete encased steel beams, concrete abutments and hammerhead piers.

Was the bridge constructed in response to significant events in Maryland or local history?

Metal girder bridges were most likely introduced and first popularized in Maryland by the state's major railroads of the nineteenth century including the Baltimore and Susquehanna, its successor the Northern Central, and the Baltimore and Ohio Railroad. Bridge engineering historians have documented the fact that James Milholland (or Mulholland) erected the earliest plate girder span in the United States on the Baltimore and Susquehanna Railroad in 1846 at Bolton Station, near present-day Mount Royal Station. The sides (web) and bottom flange of Milholland's 54-foot-long span were wholly of wrought iron and included a top flange reinforced with a 12x12-inch timber. Plates employed in the bridge were 6 feet deep and 38 inches wide, giving the entire bridge a total weight of some 14 tons. Milholland's pioneering plate girder cost \$2,200 (Tyrrell 1911:195). By December 31, 1861, the Northern Central Railroad, which succeeded the Baltimore and Susquehanna, maintained an operating inventory in Maryland of 50 or more bridges described simply as "girder" spans, in addition to a number of Howe trusses. Most of these were probably iron girder bridges; the longest were the 117-foot double-span bridge over Jones Falls and the 106-foot double-span girder bridge at Pierce's Mill (Gunnarson 1990:179-180).

As in the nation, girder bridge technology in Maryland was quickly adapted to cope with the increasingly heavy traffic demands of the twentieth century caused by automobile and truck traffic. The 1899 Maryland Geological Survey report on highways noted that "there are comparatively few I-beam bridges, one of the cheapest and best forms for spans less than 25 or 30 feet" (Johnson 1899:206). Interestingly, the report also urged construction of a composite metal, brick, and concrete bridge, noting that "no method of construction is more durable than the combination of masonry and I-beams, between which are transverse arches of brick, the whole covered with concrete, over which is laid the roadway" (Johnson 1899:206). Whether any such bridges (transitional structures between I-beams and reinforced concrete spans) were built is unknown.

Official state and county highway reports—issued between 1900 and the early 1920s through the Highway Division of the Maryland Geological Survey and its successor, the State Roads Commission—generally do not reference or describe girder construction. An analysis of the current statewide listing of county and municipal bridges (a listing maintained by the State Highway Administration) reveals that 48 county bridges, out of the total of 141 approximately dated to "1900" by county engineers, were listed as steel girder, steel stringer, or variants of such terms. (It should

be noted that the "1900" date is often given when no exact date is pinpointed for a bridge that is clearly old). A grand total of 200 bridges (including "steel culverts"), out of 550 bridges dated on the county list between 1901 and 1930, were described as steel beam, steel girder, or steel stringer and girder varieties. The total suggests that among the various highway bridge types built in the early twentieth century metal girder bridges in Maryland between 1900 and 1930 were second in popularity only to reinforced concrete bridges. However, these numbers must be interpreted with caution, as they do not necessarily include all county and municipal bridges.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

The bridge is located in an area which does not appear to be eligible for historic designation.

Is the bridge a significant example of its type?

The bridge is a potentially significant example of a metal girder bridge, possessing a high degree of integrity.

Does the bridge retain integrity of important elements described in Context Addendum?

The bridge retains the character-defining elements of its type, as defined by the Statewide Historic Bridge Context, including concrete encased metal girders, concrete abutments and concrete hammerhead piers.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?

This bridge is a significant example of the work of the manufacturer, designer, and/or engineer.

Should the bridge be given further study before an evaluation of its significance is made?

No further study of this bridge is required to evaluate its significance.

County inspection/bridge files	X	SHA inspection/bridge files	
Other (list):		-	

Gunnarson, Robert

BIBLIOGRAPHY:

1990 The Story of the Northern Central Railway, From Baltimore to Lake Ontario. Greenberg Publishing Co., Sykesville, Maryland.


Johnson, Arthur Newhall

The Present Condition of Maryland Highways. In Report on the Highways of Maryland. Maryland Geological Survey, The Johns Hopkins University Press, Baltimore.

Tyrrell, Henry G.
1911 History of Bridge Engineering. Published by author, Chicago.

SURVEYOR:

Date bridge record	ed <u>2/25/97</u>	
Name of surveyor	Caroline Hall/Tim	Tamburrino
Organization/Addr	ess P.A.C. Spero &	Co., 40 W. Chesapeake Avenue, Baltimore, MD 21204
Phone number (410) 296-1685	FAX number (410) 296-1670





1 11-12 -61 2 (M-150) FEACH TREE ROAD OVER CONT RAILRIAT 3 MONTGOMERY CE, ME - TIM TAMPUKKIN 5 3-97 6 MO SHPO

7. SOUTH APPROACH



1 1/4=12= 51 2 (M. 150) HEACH TREE ROAD OVER CENT RAILROAD B. MONTGONERY CO, MD U TIM TAMBURR K. 5 3 97 6 MD SHPO T NORTH LEPROACH 8 20 5



M 12-51 2 (M-150) PEACH TREE ROAD WIR COST RALBOAD 3. MENT COMERY CO MD I TIM TAMBURENO 5.3.97 6. MO SHPO 7 WEST ELEVATION 8 3 4 5



M 12-5 2 (M- 150) PEACH TREE ROAD IVER CONTRANDICAD 3 MONGOMERY CO ME 4 TIM TAKE KEND 5. 3.97 6 MD 54PD 7 SUPERSTRUCTURE EAST ELEVATION 8 4315



```
M. 12 - 51
2 (M-150) PEACH TEEE ROAD OVER CONT RAILBOAT
3. MONTGOMERY CO, MP
4 TM TANBURR NO
5.3.97
6. MD SHPD
  EAST ELEVATION
```

8, 505

INDIVIDUAL PROPERTY/DISTRICT MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM

Property/District Name: <u>Peach Tree Road over CSXT Railroad.</u> Survey Number: <u>M:12-51</u>	<u>Bridge #M-150</u>
Project: Bridge Replacement	Agency: MO Cnty. DPW
Site visit by MHT Staff: X no yes Name	Date
Eligibility recommended Eligibility not recommend	ded X
Criteria:ABXC _X_D Considerations:A None	_BCDEFG
Justification for decision: (Use continuation sheet if necessary and	d attach map)
Based on the information provided, the Peach Tree Road over concrete rolled metal girder bridge with a concrete deck, stee abutments. The last report produced for the bridge indicates that on the bridge and thus the Peach Tree Road Bridge has all ordinarily make it eligible for the National Register. Indeed, P.A. the bridge's eligiblity on the 1997 Historic Bridge Inventory sur concrete has begun to fail, and thus the integrity of the materials it eligible for the National Register under Criterion C. Furthermore within the bridge, and therefore it is not eligible for the National Register.	el railing, hammerhead piers and no major alterations have occurred of its major CDEs, which would A.C. Spero and Co. recommended vey form. However, the bridge's s not sufficient to make the bridge of no known archeological sites are
Documentation on the property/district is presented in: Project R	eview and Compliance
Prepared by: P.A.C. Spero & Co. and MO. Cnty. DPW (M	Manuel Monasi)
Anne E. Bruder 3/2	2/98
Reviewer, Office of Preservation Services	Date
NR program concurrence: Yes no not applicable	
Peter 3 Kenty	3/2/98
Reviewer, NR program	Date

duy

Survey	No.	M:12-51

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA - HISTORIC CONTEXT

1.	Geographic Region:	
	_ Eastern Shore	(all Eastern Shore counties, and Cecil)
	_ Western Shore	(Anne Arundel, Calvert, Charles, Prince George's and St. Mary's)
X	Piedmont	(Baltimore City, Baltimore, Carroll,
		Frederick, Harford, Howard, Montgomery)
	Western Maryland	(Allegany, Garrett and Washington)
II.	Chronological/Developmental	Periods:
***	_ Paleo-Indian	10000-7500 B.C.
	_ Early Archaic	7500-6000 B.C.
	_ Middle Archaic	6000-4000 B.C.
	_ Late Archaic	4000-2000 B.C.
	_ Early Woodland	2000-500 B.C.
	_ Middle Woodland	500 B.C A.D. 900
-	_ Late Woodland/Archaic	A.D. 900-1600
	_ Contact and Settlement	A.D. 1570-1750
	_ Rural Agrarian Intensification	A.D. 1680-1815
	_ Agricultural-Industrial Transition	
_X	Industrial/Urban Dominance	A.D. 1870-1930
<u>X</u>	Modern Period	A.D. 1930-Present
	_ Unknown Period (prehistor	ic historic)
ш.	Prehistoric Period Themes:	IV. Historic Period Themes:
	_ Subsistence	Agriculture
	_ Settlement	X Architecture, Landscape Architecture,
		and Community Planning
	_ Political	Economic (Commercial and Industrial)
	_ Demographic	Government/Law
***************************************	_ Religion	Military
•	_ Technology	Religion
	_ Environmental Adaptation	Social/Educational/Cultural
		X_ Transportation
V. R	desource Type:	
	Category: <u>Structure</u>	
	Historic Environment: Rural	
	Historic Function(s) and Use(s)	Bridge/Transportation
	Known Dagion Course:	



Photo A: View of 14-foot wide deck.



Photo B: View of deck indicates extensive cracking and spalling.



Photo C: View of existing substandard $20^{\circ}7^{\circ}$ vertical clearance and $8^{\circ}6^{\circ}$ horizontal clearance over the CSXT railroad tracks.



Photo D: View of bridge indicating Gunite repairs, severe spalling, and random transverse cracking.